Atty: Bernstein; Tel.: 202-293-7060

FIG.1(a)





FIG.1(b)



Atty: Bernstein; Tel.: 202-293-7060

FIG.2(a)




FIG.2(b)




FIG.3(a)





FIG.3(b)



10/542576

FIG.4(a)





FIG.4(b)



10/542576

FIG.5(a)





FIG.5(b)



6/19






FIG.7



7/19

10/542576




ω. <u>Ό</u>

10/542576

8/19

The state of the s



6.DI-

9/19

FIG.10





FIG.11





10/542576

10/19

FIG.12


THE LOW SERVICE STREET





11/19


10/542576




12/19

10/542576

FIG.15







13719

10/542576

FIG.17







10/542576

14/19

FIG.19





15/19

10/542576

FIG.21(a)






FIG.21(b)




16/19

FIG.22



10/542576


FIG.23



18/19

1 1 1 1 mile

FIG.24



10/542576

19/19

FIG.25(a)

. 3




FIG.25(b)

